

This chart is intended to be used as a reference for the new SpeedStream branded products and which FlowPoint products they replace. Please be sure to look at the entire sheet to the right...

Last Modified on: 5/3/00

New Efficient Products				Old FlowPoint Products			
Efficient Part Number	Efficient Description	First Customer Ship / Gen. Avail Date		FlowPoint Part Number	FlowPoint Description	Discontinuation Date	Last Buy Date
				ISDN Routers			
None				128-11 / FP110	ISDN Bridge / Router with S/T Interface - No POTS	9/1/00	8/1/00
None				128-12 / FP121	ISDN Bridge / Router with U Interface - No POTS	9/1/00	8/1/00
None				128-13 / FP112	ISDN Bridge / Router with S/T Interface - 2 POTS Ports	9/1/00	8/1/00
None				128-14 / FP123	ISDN Bridge / Router with U Interface - 2 POTS Ports	9/1/00	8/1/00
None				128-15 / FP114	ISDN Bridge / Router with S/T Interface & 4 Port HUB	9/1/00	8/1/00
				ADSL-CAP Routers			
None			Replaces	2100-12	ADSL-CAP Router, 8 Virtual Circuits, 10Base-T LAN - Inter-operates with Nokia	1/15/00	3/15/00
None			Replaces	2100-14	Same as 2100-12 except has Direct Cell Mapping (DCM) - Inter-operates with Cabletron (Ariel) / Promatory	1/15/00	3/15/00
5351 family				SDSL Upgradable Bridges			
120-5351-004	SDSL Bridge - Single VC, 4-Port Hub, Inter-operates with Copper Mountain DSLAM (Frame Relay)	May, 2000	Replaces	2200-15	SDSL Bridge - Inter-operates with Copper Mountain	8/1/00	7/1/00
120-5351-006	SDSL Bridge - Single VC, 4-Port Hub, Inter-operates with Nortel (Promatory) DSLAM (ATM-DCM)	May, 2000	Replaces	2200-19	SDSL Bridge - Inter-operates with Promatory Comm (DCM)	8/1/00	7/1/00
120-5351-007	SDSL Bridge - Single VC, 4-Port Hub, Inter-operates with InterSpeed DSLAM (Frame Relay)	May, 2000	Replaces	2200-21	SDSL Bridge - Inter-operates with Interspeed, Inc.	Discontinued	7/1/00
120-5351-012	SDSL Bridge - Single VC, 4-Port Hub, Inter-operates with Newbridge DSLAM (ATM)	May, 2000	Replaces	2200-31	SDSL Bridge - Inter-operates with Newbridge	8/1/00	7/1/00
5700 family				Broadband Routers			
120-5711-001	Ethernet to ATM Router - Multiple VCs, 4 Port 10Base-T Hub	May, 2000	Replaces	2025-12	Ethernet to ATM Router, 8 Virtual Circuits, 10Base-T LAN	8/1/00	7/1/00
120-5781-001	Ethernet to Ethernet Router - 2 x 4-Port 10Base-T Hub	May, 2000	Replaces	SSR245	Ethernet to Ethernet Bridge / Router, 2 10Base-T LAN with 4 Port HUB and single Ethernet Port (4x1) - 2 Board Solution	8/1/00	7/1/00
5851 family				SDSL Routers			
120-5851-002	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with Nokia DSLAM (ATM)	May, 2000	Replaces	2200-12	SDSL Router, 4 Port Ethernet HUB, 6 Virtual Circuits - Inter-operates with Nokia (ATM)	8/1/00	7/1/00
120-5851-007	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with InterSpeed DSLAM (Frame Relay)	May, 2000	Replaces	2200-14	SDSL Router, 4 Port Ethernet HUB, 1 Virtual Circuit - Inter-operates with Interspeed, Inc. (HDLC)	Discontinued	7/1/00
120-5851-004	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with Copper Mountain DSLAM (Frame Relay)	May, 2000	Replaces	2200-16	SDSL Router, 4 Port Ethernet HUB, 1 Virtual Circuit - Inter-operates with Copper Mountain (Frame Relay)	8/1/00	7/1/00
120-5851-005	SDSL Router - Multiple VCs, 4-Port Hub, For Point-To-Point Applications	May, 2000	Replaces	2200-18	SDSL Router, 4 Port Ethernet HUB, 1 Virtual Circuit - For Point-To-Point Applications	8/1/00	7/1/00
120-5851-006	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with Nortel (Promatory) DSLAM (ATM-DCM)	May, 2000	Replaces	2200-20	SDSL Router, 4 Port Ethernet HUB, 1 Virtual Circuit - Inter-operates with Promatory Comm (DCM)	8/1/00	7/1/00
120-5851-007	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with InterSpeed DSLAM (Frame Relay)	May, 2000	Replaces	2200-22	SDSL Router, 4 Port Ethernet HUB, 1 Virtual Circuit - Inter-operates with Interspeed, Inc. (Frame Relay)	8/1/00	7/1/00
120-5851-008	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with Lucent Stinger DSLAM (ATM)	May, 2000	Replaces	2200-24	SDSL Router, 4 Port Ethernet HUB - Inter-operates with Lucent (ATM)	8/1/00	7/1/00
120-5851-012	SDSL Router - Multiple VCs, 4-Port Hub, Inter-operates with Newbridge DSLAM (ATM)	May, 2000	Replaces	2200-32	SDSL Router, 4 Port Ethernet HUB - Inter-operates with Newbridge (ATM)	8/1/00	7/1/00
5861 family				ADSL-DMT Routers			
120-5861-001	ADSL-DMT Router - (2/5 pinout), Multiple VCs, 4-Port Hub, Inter-operates with Alcatel DSLAM	Available Now	Replaces	SSR255-12	ADSL-DMT Router, 8 Virtual Circuits, 10Base-T LAN - Inter-operates with Alcatel (US version - 2/5 pin out)	8/1/00	7/1/00
120-5861-002	ADSL-DMT Router - (3/4 pinout), Multiple VCs, 4-Port Hub, Inter-operates with Alcatel DSLAM	Available Now	Replaces	SSR255-14	ADSL-DMT Router, 8 Virtual Circuits, 10Base-T LAN - Inter-operates with Alcatel (US & ROW version - 3/4 pin out)	8/1/00	7/1/00
5871 family				IDSL Routers			
120-5871-002	IDSL Router - U Interface & 4 Port HUB - Inter-operates with Nokia and Other DSLAM	Available Now	Replaces	144-16	IDSL Router with U Interface & 4 Port HUB - Inter-operates with Nokia	Discontinued	No Last-Buy
120-5871-003	IDSL Router - U Interface & 4 Port HUB - Inter-operates with Copper Mountain DSLAM	Available Now	Replaces	144-18	IDSL Router with U Interface & 4 Port HUB - Inter-operates with Copper Mountain	Discontinued	No Last-Buy
7451 family				SDSL IADs			

120-7451-001	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Nokia (ATM DSLAM) & Jetstream (Voice Gateway)	May, 2000	Replaces	2200V-1201	SDSL IAD, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with Jetstream (Voice Gateway) & Nokia (ATM)	6/1/00	No Last-Buy
120-7451-002	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Nokia (ATM DSLAM) & CopperCom (Voice Gateway)	May, 2000	Replaces	2200V-1202	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with CopperCom (Voice Gateway) & Nokia (ATM)	6/1/00	No Last-Buy
120-7451-004	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Copper Mountain (Frame Relay DSLAM) & Jetstream (Voice Gateway)	May, 2000	Replaces	2200V-1601	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with Jetstream (Voice Gateway) & Copper Mountain (FR)	6/1/00	No Last-Buy
120-7451-005	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Copper Mountain (Frame Relay DSLAM) & CopperCom(Voice Gateway)	May, 2000	Replaces	2200V-1602	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with CopperCom (Voice Gateway) & Copper Mountain (FR)	6/1/00	No Last-Buy
120-7451-007	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Nortel (Promatory) (ATM DSLAM) & Jetstream (Voice Gateway)	May, 2000	Replaces	2200V-2001	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with Jetstream (Voice Gateway) & Promatory (DCM)	6/1/00	No Last-Buy
120-7451-008	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Nortel (Promatory) (ATM DSLAM) & CopperCom (Voice Gateway)	May, 2000	Replaces	2200V-2002	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with CopperCom (Voice Gateway) & Promatory (DCM)	6/1/00	No Last-Buy
120-7451-025	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Newbridge (ATM DSLAM) & Jetstream (Voice Gateway)	May, 2000	Replaces	2200V-3201	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with Jetstream (Voice Gateway) & Newbridge (ATM)	6/1/00	No Last-Buy
120-7451-026	SDSL IAD - 4 Voice Ports, IP Router w/ 4 Port Ethernet HUB, Inter-operates with Newbridge (ATM DSLAM) & CopperCom (Voice Gateway)	May, 2000	Replaces	2200V-3202	SDSL Router, 4 Port Ethernet HUB, 4 Voice Ports - Inter-operates with CopperCom (Voice Gateway) & Newbridge (ATM)	6/1/00	No Last-Buy